

The following emulator, known as “ADTRON” has a known failure rate because of a wrong timing synch between the compact flash and the emulator, that leads the host machinery to write bad sectors. Customers are urgently alerted about this risky and faulty hardware.









