The following emulator, known as "SINTECHI", aka "SDCARD-to-IDE", aka "SDCARD-to-PATA", has a proven 100% failure rate (given enough data being written > 1MB) because of a wrong timing synch between the sdcard and the emulator, that leads the host machinery to write bad sectors, almost immediately, and crash. Customers are urgently alerted about this risky and faulty hardware.

Same problem is suspected to be affecting all the products based on the "SINTECHI" controller, that has been implemented inside: CF emulators, SDCARD emulators, CF standalone units.

Proprietà - SINTECHI HighSpeed SD to USB Device

Generale | Criteri | Volumi | Driver | Dettagli

SINTECHI HighSpeed SD to USB Device

ID istanza periferica

&VEN_SINTECHI&PROD__HIGHSPEED_SD_TO&REV_\EC23225343218